

**TERMOMETRO BIMETALLICO A IMMERSIONE**  
 - Gambo posteriore con guaina Ø 1/2"



| lungh. gambo cm | scala °C | cassa Ø | codice  |
|-----------------|----------|---------|---------|
| 5               | 0÷120    | 80      | 2537.05 |
| 10              | 0÷120    | 80      | 2537.10 |
| 5               | 0÷60     | 80      | 2662.05 |
| 10              | 0÷60     | 80      | 2662.10 |
| 5               | 0÷120    | 100     | 2610.05 |
| 10              | 0÷120    | 100     | 2610.10 |
| 5               | -30÷50   | 80      | 2539.05 |
| 10              | -30÷50   | 80      | 2539.10 |
| 10              | -30÷50   | 100     | 2669.10 |

**TERMOMETRO A CONTATTO**  
 - Molla fissaggio a bracciale



| scala °C | cassa Ø | codice  |
|----------|---------|---------|
| 0÷120    | 63      | 2541.00 |

**TERMOMETRO A CAPILLARE**  
 - Campo di misura: 0° ÷ 120°C  
 - Lunghezza capillare: 1000 mm  
 - Bulbo: Ø 6,5 x 26 mm



| Ø mm | codice  |
|------|---------|
| 43   | 2546.43 |
| 57   | 2546.57 |

**TERMOMETRO BIMETALLICO A IMMERSIONE**  
 - Gambo radiale con guaina Ø 1/2"



| lungh. gambo cm | scala °C | cassa Ø | codice  |
|-----------------|----------|---------|---------|
| 5               | 0÷120    | 80      | 2538.05 |
| 10              | 0÷120    | 80      | 2538.10 |
| 5               | 0÷60     | 100     | 2676.05 |
| 10              | 0÷60     | 100     | 2676.10 |
| 5               | -30÷50   | 100     | 2676.06 |
| 10              | -30÷50   | 100     | 2676.11 |
| 5               | 0÷120    | 100     | 2676.07 |
| 10              | 0÷120    | 100     | 2676.12 |

**TERMOMANOMETRO**  
 - Attacco radiale  
 - Con guaina a rubinetto Ø 1/2"



| scala bar | scala °C | cassa Ø | codice  |
|-----------|----------|---------|---------|
| 0÷6       | 0÷120    | 80      | 2544.06 |

**TERMOMANOMETRO**  
 - Attacco posteriore  
 - Con guaina a rubinetto Ø 1/2"



| scala bar | scala °C | cassa Ø | codice  |
|-----------|----------|---------|---------|
| 0÷6       | 0÷120    | 80      | 2545.06 |

**POZZETTO**  
 - Ø 1/2"  
 - Completo di molla a frizione per sonda Ø 10 mm



| lungh. gambo cm | codice  |
|-----------------|---------|
| 5               | 2540.05 |
| 10              | 2540.10 |
| 15              | 2540.15 |
| 20              | 2540.20 |

**GUAINA SAGOMATA**  
 - Ø 1/2"



| lungh. gambo cm | codice  |
|-----------------|---------|
| 12              | 2562.03 |

**STAFFA ANCORAGGIO DEI TERMOMETRI SUI CANALI**



| codice  |
|---------|
| 2615.00 |

**MANOMETRO Ø 63**

- Cassa in ABS
- Attacco radiale Ø 1/4"
- Temperatura di impiego: -20° ÷ +80°C

| scala bar | codice                  |
|-----------|-------------------------|
| 0/1,6     | <a href="#">4001.02</a> |
| 0/2,5     | <a href="#">4001.03</a> |
| 0/4       | <a href="#">4001.04</a> |
| 0/6       | <a href="#">4001.06</a> |
| 0/10      | <a href="#">4001.10</a> |
| 0/16      | <a href="#">4001.16</a> |

**MANOMETRO Ø 80**

- Cassa in ABS
- Attacco radiale Ø 3/8"
- Temperatura di impiego: -20° ÷ +80°C

| scala bar | codice                  |
|-----------|-------------------------|
| 0/1,6     | <a href="#">4002.02</a> |
| 0/2,5     | <a href="#">4002.03</a> |
| 0/4       | <a href="#">4002.04</a> |
| 0/6       | <a href="#">4002.06</a> |
| 0/10      | <a href="#">4002.10</a> |
| 0/16      | <a href="#">4002.16</a> |
| 0/25      | <a href="#">4002.25</a> |
| 0/40      | <a href="#">4002.40</a> |

**MANOMETRO Ø 100**

- Cassa in acciaio
- Attacco radiale Ø 1/2"
- Temperatura di impiego: -20° ÷ +80°C

| scala bar | codice                  |
|-----------|-------------------------|
| 0/6       | <a href="#">4036.06</a> |
| 0/10      | <a href="#">4036.10</a> |
| 0/16      | <a href="#">4036.16</a> |
| 0/25      | <a href="#">4036.25</a> |
| 0/40      | <a href="#">4036.40</a> |
| 0/60      | <a href="#">4036.60</a> |

**MANOMETRO Ø 63**

- Cassa in ABS
- Attacco posteriore Ø 1/4"
- Temperatura di impiego: -20° ÷ +80°C

| scala bar | codice                  |
|-----------|-------------------------|
| 0/4       | <a href="#">4003.04</a> |
| 0/6       | <a href="#">4003.06</a> |
| 0/10      | <a href="#">4003.10</a> |
| 0/16      | <a href="#">4003.16</a> |

**VUOTOMETRO**

- Attacco radiale
- Temperatura di impiego: -20° ÷ +80°C

| scala bar | attacco | Ø  | codice                  |
|-----------|---------|----|-------------------------|
| -1/0      | 1/4"    | 63 | <a href="#">4019.06</a> |
| -1/0      | 3/8"    | 80 | <a href="#">4019.08</a> |

**MANOMETRO ALLA GLICERINA**

- Cassa inox
- Attacco radiale in ottone
- Temperatura di impiego: -20° ÷ +80°C

| CASSA Ø 63 |         |                         | CASSA Ø 100 |                         |
|------------|---------|-------------------------|-------------|-------------------------|
| scala bar  | attacco | codice                  | attacco     | codice                  |
| 0/6        | 1/4"    | <a href="#">4037.06</a> | 1/2"        | <a href="#">4038.06</a> |
| 0/10       | 1/4"    | <a href="#">4037.10</a> | 1/2"        | <a href="#">4038.10</a> |
| 0/16       | 1/4"    | <a href="#">4037.16</a> | 1/2"        | <a href="#">4038.16</a> |
| 0/25       | 1/4"    | <a href="#">4037.25</a> | 1/2"        | <a href="#">4038.25</a> |
| 0/40       | 1/4"    | <a href="#">4037.40</a> | 1/2"        | <a href="#">4038.40</a> |
| 0/60       | 1/4"    | <a href="#">4037.60</a> | 1/2"        | <a href="#">4038.60</a> |

**RUBINETTO PORTAMANOMETRO**

- Con flangia per manometro.
- Tappo di sicurezza e premistoppa
- Pressione max. di esercizio: 16 bar
- Temperatura di impiego: 4° ÷ 90°C

| Ø    | codice                  |
|------|-------------------------|
| 1/4" | <a href="#">2516.14</a> |
| 3/8" | <a href="#">2516.17</a> |
| 1/2" | <a href="#">2516.21</a> |

**SERPENTINO AMMORTIZZATORE**

- Corpo in rame
- PN 25
- Temperatura di impiego: 0° ÷ 120°C

| Ø    | codice                  |
|------|-------------------------|
| 1/4" | <a href="#">2517.14</a> |
| 3/8" | <a href="#">2517.17</a> |
| 1/2" | <a href="#">2517.21</a> |